

[INSTRUCTION MANUAL]

FINE Sodick

NC-EDM

A7C

MACHINE SECTION



FINE Sodick

SODICK Co., Ltd.

Vol.1.1

CONTENTS

1. ITEMS TO BE CHECKED BEFORE USE	1
1) Location of Machine	2
2) Incidental Work	2
3) Precautions for Safety	3
4) Check on Safety Devices	4
5) Inspection of Safety Devices	5
6) Prohibited Matters	5
2. GENERAL DESCRIPTION	6
1) Appearance of Machine	7
2) Designation and Description of Parts	8
3. SPECIFICATIONS	11
1) Main Body of Machine	12
2) Service Tank	13
3) NC Power Unit	13
4) Principal Dimensions	13
4. TRANSPORTATION AND INSTALLATION	15
1) Transportation	16
2) Location	18
3) Installation	21

5. OPERATING INSTRUCTIONS	28
1) Designation of Each Axis and Its Direction	29
2) NC Power Unit "MARK XI"	30
3) Machining Tank	39
4) Service Tank	43
5) Dielectric Fluid	47
6. PREPARATION FOR MACHINING	51
1) Setting of Electrode	52
2) Setting of Workpiece	54
7. MAINTENANCE AND INSPECTION	55
1) Inspection Items	56
2) Filter Change	57
3) Lubrication	58
4) Consumables	61