


REISHAUER

DESCRIPTION AND WORKING INSTRUCTIONS
OF THE
UNIVERSAL THREAD AND GRINDING MACHINE
TYPE



	Page:
Data of the machine	4
Setting up and putting into service	5
Electrical equipment	7
Control	9
Grinding slide	11
Construction	11
Gear box for the grinding spindle drive	11
Grinding spindle, design	12
Dismantling the grinding spindle and the bearing bushes	12
Re-assembling, adjusting the bearing play	13
Approach devices	14
Manuel approach device	14
Fine approach device	14
Automatic approaching device	15
Copying device	16
Grinding with cams	16
Grinding wheel withdrawal	17
Grinding with fixed stop	18
Workpiece drive	19
A. Normal thread	19
1. Longitudinal grinding, pitch $0.6 \pm 8 \text{ mm}$ $0.024 \pm 0.315''$	19
2. Two-way grinding, pitch $0.3 \pm 8 \text{ mm}$ $0.012 \pm 0.315''$	20
B. Steep thread	21
3. Longitudinal grinding, pitch more than 8 mm $0.315''$	21
4. Two-way grinding, pitch more than 8 mm $0.315''$	21
C. Plunge cut grinding and thread with helical flutes	22
5. Plunge cut grinding, pitch $0.6 \pm 8 \text{ mm}$ $0.024 \pm 0.315''$	22
6. Thread with helical flutes, pitch $0.3 \pm 8 \text{ mm}$ $0.012 \pm 0.315''$	23
Locking the lead screw	24
Workpiece speed	25
Device for compensating the back lash	25
Adjusting the axial bearing at the lead screw	29
Braking device	29

metr. / inch

6 78139

REISHAUER

Page:

Table slide	29
Setting the grinding wheel into pre-machined threads	31
Stopping selector	32
Work impulse	32
Reversing the table slide, emergency disengaging	33
Headstock, Workspindle	33
Dividing device at the work headstock	34
Setting the bearing play at the working spindle	34
Tailstock	34
Relief grinding device	35
Change gears	36
Lighting, Profile control	37
Cooling	37
Automatic stop valve for the cooling-oil	38
Grinding wheels	39
Choice	39
Flanges	39
Balancing	39
Truing the single-rib wheel	40
Hand truing device	40
Construction and method of working	40
Truing profiles with rounded peaks	42
The truing of trapezoidal profiles	43
Making concave wheel profiles	43
Grinding with the single-rib wheel	44
Setting the pitch angle	44
Setting the table feed and the stops	44
Relief grinding device	44
Setting the workpiece with respect to the relief grinding cam	45
Relief grinding of tools with helical grooves	46
Relief grinding of workpieces with helical grooves	47

m.c. / m.c.

6 74986

	Page:
Grinding with multi-ribbed wheels	47
Grinding according to the infeed method	48
Setting	48
Setting the grinding travel	48
Conventional grinding of left-hand threads	49a
Profiling the multi-ribbed wheel	50
Construction and method of working of the crushing device	50
Crushing rolls	51
Grinding the crushing rolls	51
Longitudinal grinding with the multi-ribbed wheel	53
Two-way grinding with the multi-ribbed wheel	53
Profiling of multi-ribbed wheels for longitudinal grinding	54
Profiling the multi-ribbed wheel for two-way grinding	54
Errors when grinding	55
Attendance	56
Lubrication and checking plan	58
Illustrations, tables etc.	from 100