

PROGRAMMING MANUAL

for

MAZATROL M PLUS

MAZATROL PROGRAMMING

Manual No. : H733PG0013E

Before using this machine and equipment, fully understand the contents of this manual to ensure proper operation. Should any questions arise, please ask the nearest Technical/Service Center.

IMPORTANT NOTICE

1. Be sure to observe the safety precautions described in this manual and the contents of the safety plates on the machine and equipment. Failure may cause serious personal injury or material damage. Please replace any missing safety plates as soon as possible.
2. No modifications are to be performed that will affect operation safety. If such modifications are required, please contact the nearest Technical/Service Center.
3. For the purpose of explaining the operation of the machine and equipment, some illustrations may not include safety features such as covers, doors, etc. Before operation, make sure all such items are in place.
4. This manual was considered complete and accurate at the time of publication, however, due to our desire to constantly improve the quality and specification of all our products, it is subject to change or modification. If you have any questions, please contact the nearest Technical/Service Center.
5. Always keep this manual near the machinery for immediate use.
6. If a new manual is required, please order from the nearest Technical/Service Center with the manual No. or the machine name, serial No. and manual name.

Issued by *Manual Publication Section, Yamazaki Mazak Corporation, Japan*

PART 2 MAZATROL PROGRAM FUNCTIONS

1.	CALLING UP AND THE END OF THE PROGRAM DISPLAY	1-1
1-1	Listing Mode and Creating Mode	1-1
1-2	Calling Up the PROGRAM Display (Listing Mode)	1-1
1-3	Calling Up the PROGRAM Display (Creating Mode)	1-2
1-4	End of the Program Creation	1-3
2.	EDITION OF DATA	2-1
2-1	Cursor Movement	2-1
2-1-1	Case of listing mode	2-1
2-1-2	Case of creating mode	2-2
2-2	Editing	2-2
2-2-1	Editing functions and menus	2-2
2-2-2	Search	2-3
2-2-3	Insertion	2-9
2-2-4	Deletion	2-12
2-2-5	Copy	2-15
2-2-6	End of program	2-21
3.	WINDOW FUNCTIONS	3-1
3-1	MAZATROL Help Window	3-1
3-2	Tool File Window	3-2
3-3	Tool Data Window	3-3
3-4	Tap Nominal Diameter Window	3-4
4.	PROGRAM CREATION	4-1
4-1	Types of Units	4-1
4-2	Common Unit	4-2
4-3	Basic Coordinates System Unit	4-6
4-4	Auxiliary Coordinates System Unit	4-6
4-5	Types of the Machining Unit	4-7
4-6	Point Machining Unit	4-8
4-6-1	Types of point machining units	4-8
4-6-2	Procedure for selecting point machining unit	4-9
4-6-3	Unit data and automatic tool development	4-10
1.	Drilling unit (DRILLING)	4-10
2.	RGH CBOR machining unit (RGH CBOR)	4-11
3.	RGH BCB machining unit (RGH BCB)	4-13
4.	Reaming unit (REAMING)	4-14
5.	Tapping unit (TAPPING)	4-19
6.	Boring unit (BORING)	4-21
7.	Back boring unit (BK-CBORE)	4-29
8.	Circular milling unit (CIRC MILL)	4-32
9.	Counterbore-tapping unit (CBOR-TAP)	4-34

4-6-4	Tool sequence data	4-36
4-6-5	Tool path	4-41
4-6-6	Shape sequence	4-65
4-7	Line Machining Units	4-82
4-7-1	Types of line machining units	4-82
4-7-2	Procedure for selecting line machining unit	4-83
4-7-3	Unit data, automatic tool development and tool path	4-83
	1. Central linear machining unit (LINE CTR)	4-83
	2. Right-hand linear machining unit (LINE RGT)	4-86
	3. Left-hand linear machining unit (LINE LFT)	4-89
	4. Outside linear machining unit (LINE OUT)	4-92
	5. Inside linear machining unit (LINE IN)	4-99
	6. Right-hand chamfering unit (CHMF RGT)	4-105
	7. Left-hand chamfering unit (CHMF LFT)	4-108
	8. Outside chamfering unit (CHMF OUT)	4-111
	9. Inside chamfering unit (CHMF IN)	4-116
4-7-4	Line machining tool sequence data	4-121
4-7-5	Line machining shape sequence data	4-124
4-7-6	Precautions in line machining	4-124
4-7-7	Automatic corner override	4-128
4-8	Face Machining Units	4-129
4-8-1	Types of face machining units	4-130
4-8-2	Procedure for selecting face machining unit	4-130
4-8-3	Unit data, automatic tool development and tool path	4-131
	1. Face milling unit (FACE MIL)	4-131
	2. End milling-top unit (TOP EMIL)	4-136
	3. End milling-step unit (STEP)	4-140
	4. Pocket milling unit (POCKET)	4-146
	5. Pocket milling-mountain unit (PCKT MT)	4-153
	6. Pocket milling-valley unit (PCKT VLY)	4-162
	7. End milling-slot unit (SLOT)	4-171
4-8-4	Face machining tool sequence data	4-176
4-8-5	Precautions in face machining	4-180
4-8-6	Override in case of the overall width cutting	4-186
4-8-7	Definitions of forms in line machining and face machining units	4-188
4-9	End Unit	4-209
4-10	Special Mode Unit	4-210
4-10-1	Procedure for calling up the special mode unit	4-210
4-10-2	M code unit	4-211
4-10-3	Sub-program unit	4-212
4-10-4	Pallet changing unit	4-213
4-10-5	Indexing unit	4-213
4-10-6	Process end unit	4-215
4-11	Manual Program Mode Unit	4-217
4-11-1	Input procedure	4-217

4-11-2	Structure of the unit	4-218
4-11-3	Composition of the sequence	4-219
4-12	MMS Unit	4-220
4-12-1	Procedure for calling up the MMS unit	4-220
4-12-2	Composition of the unit	4-221
4-12-3	Composition of the sequence	4-221
4-12-4	Measurement of length of feeler	4-222
4-12-5	Feeler calibration measurement	4-224
4-12-6	Type of measurement	4-227
5.	PRIORITY FUNCTION FOR THE SAME TOOL	5-1
5-1	Priority Machining Order	5-1
5-2	Priority Machining Zone	5-3
5-3	Editing Function and Input Method of Priority Numbers	5-5
5-3-1	Input of priority numbers	5-5
5-3-2	Assignment of priority numbers	5-6
5-3-3	Change of priority numbers	5-7
5-3-4	Deletion of all the priority numbers	5-8
5-3-5	How to use the SUB-PROG PROC END function	5-8
5-4	Relation between the Sub-program Unit and the Priority Machining Function	5-10
5-5	Relation between the Indexing Unit and the Priority Machining Function	5-11
5-6	Relation between the M Code Unit and the Priority Machining Function	5-12
5-7	Relation between Multi-workpiece Machining and the Priority Machining function	5-13
6.	COORDINATES MEASUREMENT FUNCTION	6-1
6-1	Method of Measurement of Coordinates by TEACH Function	6-1
6-2	Method of Measurement of Coordinates by MDI-MMS	6-4
7.	TPC DATA CREATION	7-1
7-1	Setting Tool Path Control (TPC) Data	7-1
7-2	Description of Each TPC Data Item	7-4
8.	BACKGROUND PROGRAMMING	8-1
9.	CASE OF APPEARANCE OF ALARM	9-1
10.	THREE-DIGIT G-FORMAT	10-1
10-1	Outline	10-1
10-2	Detailed Description	10-1
10-3	Three-Digit G-Format of MAZATROL Program	10-2
10-4	Various Data Description Using G10	10-15

APPENDIX

APPENDIX 1	LIST OF M CODES	APPX-1
APPENDIX 2	PROGRAM EXAMPLES	APPX-4
APPENDIX 3	WHAT TO DO IN SUCH A CASE?	APPX-8