

CNC SYSTEMS

OSP5020L

OSP500L-G

GAUGING MANUAL (6th Edition)

TABLE OF CONTENTS

	<u>PAGE</u>
PART I AUTOMATIC WORK GAUGING & TOUCH SETTER M/A	1
SECTION 1 AUTOMATIC WORK GAUGING	1
1. OUTLINE OF AUTOMATIC WORK GAUGING SYSTEM	2
1-1. OUTLINE	2
1-2. CONFIGURATION	2
1-3. GAUGING PRINCIPLE	3
2. PROGRAMMING	6
2-1. PROGRAMMING FORMAT FOR A MODEL NOT FEATURING TOOL LIFE MANAGEMENT	6
2-1-1. One-Saddle (1S) Specification	6
2-1-2. Two-Saddle (2S) Specification	7
2-2. PROGRAMMING FORMAT FOR A MODEL FEATURING TOOL LIFE MANAGEMENT	8
2-2-1. One-Saddle (1S) Specification	8
2-2-2. Two-Saddle (2S) Specification	10
3. MASTER RING GAUGING CYCLE PROGRAM	12
3-1. MASTER RING GAUGING CYCLE - ID	12
3-2. MASTER RING GAUGING CYCLE - OD	13
3-3. GAUGING CYCLE G30	14
3-4. GAUGING CYCLE SUBPROGRAMS	15
3-4-1. ORGIA	15
3-4-2. ORGOA	19
3-4-3. ORNGB	20
3-5. MASTER RING GAUGING PROGRAM FOR MODELS FEATURING TOOL LIFE MANAGEMENT	21
3-6. MASTER RING GAUGING CYCLE "START" CONDITIONS	22
4. WORK GAUGING CYCLE PROGRAM (RADIUS GAUGING PROGRAM)	23
4-1. WORK GAUGING CYCLE	23
4-2. GAUGING CYCLE SUBPROGRAMS	24
4-2-1. OWMXA	24
4-2-2. OWMZA	28
4-2-3. OWXBA	29
4-2-4. OWXBB	29
4-2-5. OWZBA	30
4-2-6. OWZBB	30

	<u>PAGE</u>
4-3. WORK GAUGING PROGRAM FOR A MODEL FEATURING TOOL LIFE MANAGEMENT	32
4-3-1. Differences from Gauging Cycle for the Control Not Featuring Tool Life Management	32
4-3-2. Additional Functions for the Control Featuring Tool Life Management	35
4-4. CONDITIONS FOR WORK GAUGING CYCLE EXECUTION	37
4-5. TRIAL CUT GAUGING CYCLE PROGRAM	38
4-6. CONDITIONS FOR STARTING TRIAL CUT GAUGING CYCLE	40
5. DIAMETER GAUGING CYCLE PROGRAM (IN-PROCESS WORK GAUGING)	42
SECTION 2 TOUCH SETTER CYCLE M/A	60
1. AUTOMATIC TOOL GAUGING CYCLE BY TOUCH SETTER	61
1-1. OUTLINE OF TOUCH SETTER	61
1-1-1. Outline	61
1-1-2. Construction	61
1-1-3. Gauging Principle	62
1-2. PROGRAMMING FORMAT - TOUCH SETTER A SPECIFICATION	63
1-2-1. Programming Format For A Model Not Featuring Tool Life Management	63
1-2-2. Programming Format For A Model Featuring Tool Life Management ..	65
1-3. OPERATIONS	67
1-3-1. Sensor Head	67
1-3-2. Sensor Touch Position	70
1-3-3. Basic Axis Movements	72
1-4. TOUCH SETTER INTERLOCK	76
1-5. AUTOMATIC TOUCH SETTER GAUGING CYCLE PROGRAM	77
1-5-1. Tool Offset Data Read-out Cycle	77
1-5-2. Tool Breakage Detection Cycle	81
1-5-3. Example Of Program - Two-saddle Specification	82
1-5-4. Tool Gauging Program For A Model Featuring Tool Life Management	83
1-5-5. Conditions For Automatic Touch Setter Gauging Cycle Execution ..	85
2. TOUCH SETTER MANUAL GAUGING CYCLE	88
2-1. OUTLINE	88
2-2. MANUAL TOUCH SETTER GAUGING CYCLE	89
2-3. AUTOMATIC SETTING OF DATA	92
2-4. PARAMETER SETTING	95

	<u>PAGE</u>
SECTION 3 SUBPROGRAMS OTHER THAN GAUGING CYCLES	96
1. GAUGING CYCLE START CONDITION COUNTER (SUBPROGRAM OCNCK)	97
2. RESETTNG GAUGING CYCLE START CONDITIONS (SUBPROGRAM OMSSF)	99
3. EVALUATION OF TRIAL CUT GAUGING CYCLE FOR AUTOMATIC TOOL SELECTION (SUBPROGRAM OTRCK)	100
4. EVALUATION OF AUTOMATIC TOUCH SETTER GAUGING CYCLE START CONDITION (SUBPROGRAM OTST)	101
SECTION 4 DISPLAY OF GAUGING DATA	103
1. DISPLAY OF GAUGING DATA	104
SECTION 5 DATA SETTING	107
1. MASTER RING POSITION DATA	109
2. SETTING COUNTER FOR GAUGING CYCLE ON CONDITION	110
3. SETTING OPTIONAL PARAMETER (BIT) DATA	112
3-1. GAUGING CYCLE ON PUSHBUTTON SETTING HOLD BIT	113
3-2. GAUGING CYCLE PROGRAM DISPLAY BIT	114
4. FEEDRATE IN GAUGING CYCLES	115
SECTION 6 CAUTIONS	116
SECTION 7 APPENDIX	117
1. ALARM TABLE	117
2. CONTROL STATEMENTS	124
2-1. GOTO STATEMENT	125
2-2. IF STATEMENT	126
2-3. EVALUATION OF DEFINED OR UNDEFINED LOCAL VARIABLES BY IF STATEMENT	127
2-4. CALL STATEMENT	128
2-5. RTS STATEMENT	129
2-6. CONTINUATION CODE	130

	<u>PAGE</u>
PART II AUTOMATIC ZERO OFFSET	131
1. OUTLINE	131
2. OPERATIONS	131
2-1. GAUGING CYCLE IN SINGLE-CONTACT MDOE	131
2-2. GAUGING CYCLE IN DOUBLE-CONTACT MODE	132
3. GAUGING CYCLE SUBPROGRAMS	
3-1. SUBPROGRAM OZOFA	134
3-2. SUBPROGRAM OZOFB	135
4. PROGRAMMING	136
4-1. SINGLE-SADDLE MODEL	136
4-2. TWO-SADDLE SPECIFICATION	136
PART III POST-PROCESS AUTOMATIC WORK GAUGING - 5-GRADE SIGNAL SYSTEM	137
1. SYSTEM OUTLINE	137
1-1. SUMMARY	137
1-2. SYSTEM LAYOUT	137
2. AUTO COMPENSATION OF TOOL OFFSET VALUE	139
2-1. GAUGING LAG (NO. OF WORKPIECES)	139
2-2. COMPENSATION TIMING	139
2-3. COMPENSATION PROCESS	140
2-4. COMPENSATION INVALID (IGNORE)	141
2-5. COMPENSATION AFTER TOOL AUTO INDEXING	143
3. AUTO COMPENSATION DATA SETTING AND DISPLAY	145
3-1. DATA SETTING METHOD	145
3-2. DATA SETTING RANGE	147
3-3. AUTO CORRECTION DATA DISPLAY	148
4. PROGRAM	149
5. POST-PROCESS GAUGING DATA INPUT	150
6. ALARMS AND MESSAGES	154

PAGE

PART IV	POST-PROCESS AUTOMATIC WORK GAUGING - 7-GRADE SIGNAL SYSTEM	155
1.	SYSTEM OUTLINE	155
1-1.	SUMMARY	155
1-2.	SYSTEM LAYOUT	155
1-3.	BASIC PRINCIPLES	155
2.	AUTO COMPENSATION OF TOOL OFFSET VALUE	157
2-1.	GAUGING LAG (NO. OF WORKPIECES)	157
2-2.	COMPENSATION TIMING	157
2-3.	COMPENSATION PROCESS	158
2-4.	COMPENSATION INVALID (IGNORE)	159
2-5.	CORRECTION AFTER TOOL AUTO INDEXING	161
3.	AUTO COMPENSATION DATA SETTING AND DISPLAY	163
3-1.	DATA SETTING METHOD	163
3-2.	DATA SETTING RANGE	165
3-3.	AUTO COMPENSATION DATA DISPLAY	166
4.	PROGRAM	167
5.	POST-PROCESS GAUGING DATA INPUT	168
6.	ALARMS AND MESSAGES	172

PAGE

PART V	AUTOMATIC WORK GAUGING & TOUCH SETTER M/A SOFTWARE	173
1.	OUTLINE OF GAUGING CYCLES	173
2.	VARIABLE TABLES	174
2-1.	COMMON VARIABLES (V901 - V932)	175
2-2.	SYSTEM VARIABLES 1	178
2-3.	SYSTEM VARIABLES 2	181
2-4.	SYSTEM VARIABLES 3	182
2-5.	SYSTEM VARIABLES 4	184
2-6.	INPUT/OUTPUT VARIABLES	187
3.	PRINT COMMAND	189
3-1.	PRINT OUT DATA	190
3-2.	PRINT FORMAT	191
4.	NOTES	194
4-1.	NOEX	194
4-2.	IF STATEMENT USED FOR JUDGING WHETHER LOCAL VARIABLES HAVE BEEN DEFINED OR NOT	195
4-3.	CALCULATION OF MEASURED VALUE (SENSOR CONTACT POSITION ON PROGRAM COORDINATE SYSTEM) IN GAUGING CYCLE IN Z-AXIS	196
5.	SUBPROGRAM TABLE	197
6.	FLOW CHART	200
7.	LIST	237

PAGE

PART VI	AUTOMATIC ZERO OFFSET SOFTWARE	256
1.	OUTLINE OF GAUGING CYCLE USED FOR ZERO OFFSET	256
2.	VARIABLE TABLES	257
2-1.	COMMON VARIABLES (V901 - V932)	258
2-2.	SYSTEM VARIABLES 1	
2-3.	SYSTEM VARIABLES 2	261
3.	NOTES	262
3-1.	NOEX	262
3-2.	IF STATEMENT USED FOR JUDGING WHETHER LOCAL VARIABLES HAVE BEEN DEFINED OR NOT	263
3-3.	CALCULATION OF MEASURED VALUE	264
4.	FLOW CHART	265
5.	LIST	268
PART VII	POST-PROCESS AUTOMATIC WORK GAUGING SOFTWARE - 5-GRADE SIGNAL SYSTEM	269
1.	OUTLINE OF GAUGING CYCLE	269
2.	VARIABLE TABLES	270
2-1.	COMMON VARIABLES (V901 - V932)	271
2-2.	SYSTEM VARIABLES 1	273
2-3.	SYSTEM VARIABLES 2	275
2-4.	INPUT/OUTPUT VARIABLES	276
3.	PRECAUTIONS (FOR ALL MSB OPERATIONS)	277
4.	FLOW CHART	278
5.	LIST	282

PAGE

PART VIII	POST-PROCESS AUTOMATIC WORK GAUGING SOFTWARE	
	- 7-GRADE SIGNAL SYSTEM	284
1.	OUTLINE OF GAUGING CYCLE	284
2.	VARIABLE TABLES	284
2-1.	COMMON VARIABLES (V901 - V932)	286
2-2.	SYSTEM VARIABLES 1	288
2-3.	SYSTEM VARIABLES 2	290
2-4.	INPUT/OUTPUT VARIABLES	291
3.	PRECAUTIONS (FOR ALL MSB OPERATIONS)	292
4.	FLOW CHART	292
5.	LIST	297
6.	APPLICATIONS OF MAKER SUBPROGRAMS (MSB)	299

Note: To avoid any confusion over the use of the letter "O (oh)" and figure "0 (zero)" in this manual, the numerical value "0 (zero)" is expressed as "Ø" if there is any possibility of misunderstanding.
