



NC MILLING MACHINE

PROGRAMMING INSTRUCTION MANUAL

MHA-300II

MHA-400II

MHA-500

MHA-600

MHA-800

MHA-350

MHA-450

MHA-550

MHA-650

OKK CORPORATION
3-21-9, Toyosaki, Kita-ku
Osaka, Japan

MHA-PRO-1
May, 1993-P

CONTENTS

(1)	Introduction	1
(2)	Program - Machining flowchart	2
(3)	Program	3
(1)	Fundamental knowledge	3 ~ 4
(2)	Words	4
①	Program number and sequence number	4
②	Coordinate words and controlled axes	4 ~ 5
③	Cutting feedrate	5 ~ 6
④	Compensation No. H	6
⑤	Miscellaneous functions	6 ~ 8
⑥	Preparation functions	8
1)	List of miscellaneous functions	8 ~ 11
2)	G codes	12
1	G90, G91	12 ~ 13
2	G92	14 ~ 15
3	G00	16
4	G01	16 ~ 25
5	G17, G18, G19	26
6	G02, G03	27 ~ 33
7	G04	34
8	G09	34 ~ 36
9	G28	36 ~ 37
	Compensation	38
10	G43, G44	38 ~ 39
11	Z-axis initial access motion	39
12	G45, G46, G47, G48	40 ~ 47
13	G40, G41, G42	48 ~ 73

	14	Standard fixed cycle G80	74 ~ 77
		G81, G82, G83	78 ~ 81
		G84, G85	82 ~ 85
		G86	86
		G88, G89	87
		G73	88
		G74	89 ~ 92
	15	G22, G23	93 ~ 101
(4)		Example of entire program	102 ~ 106
(5)		Exercises	107
(6)		Appendix	108
(1)		Main specifications of control unit	109 ~ 110
(2)		Data format list	111
(3)		Address code list	112
(4)		G code list	113 ~ 115
(5)		Number of rotation of main axis	116 ~ 117
(6)		NC tape (NC specifications)	118 ~ 120

<Note> "OKK-Graphic ML" is referred to as "OKK-GML" in this manual.