


WIRE-CUT EDM SYSTEMS



PROGRAMMING

MITSUBISHI ELECTRIC CORPORATION ©

(2nd version)



CONTENTS

1.	INTRODUCTION	1-1
2.	PROGRAMMING PROCEDURE	2-1
3.	PROGRAM FORMAT	3-1
4.	PROGRAM NUMBER L	4-1
5.	COORDINATE SYSTEM	5-1
6.	MOVE COMMAND	6-1
7.	WIRE DIAMETER COMPENSATION FUNCTION	7-1
8.	MACHINING SUPPORT FUNCTIONS	8-1
9.	PROGRAM SUPPORTING FUNCTIONS	9-1
10.	MULTIPLE COORDINATE SYSTEMS..... (G53 TO G59 AND G43)	10-1
11.	PREPARATORY FUNCTION G	11-1
12.	FEED SPEED FUNCTION F	12-1
13.	MISCELLANEOUS FUNCTION M	13-1
14.	MATCHING CONDITION SELECTION E	14-1
15.	COORDINATES ROTATION FUNCTION; K	15-1
16.	FIGURE SCALE SETTING FUNCTION; S	16-1
17.	TAPER ANGLE COMMAND FUNCTION; A	17-1
18.	EXECUTION SEQUENCE FOR SIMULTANEOUS COMMAND OF GRAPHIC SCALE AND COORDINATE ROTATE	18-1
19.	UPPER AND LOWER OPTIONAL SHAPE PROGRAMMING	19-1
20.	INITIAL HOLE COMPENSATION	20-1