




UNIVERSAL TOOL & CUTTER GRINDER

MODEL C-40

INSTRUCTION MANUAL



CONTENTS

	Page
1. Machine specifications	4
2. Names of operation parts and others	5
3. Main dimensions of machine and floor plan	7
4. Handling of machine	9
1) Lifting the machine	9
2) Inspection and cleaning of machine	9
3) Foundation and installation	9
4) Wiring	11
5) Lubrication	12
6) Standard equipment	15
5. Structure and operation	17
1) Electrical equipment	17
2) Mechanism of table longitudinal movement	20
3) Mechanism of grinding head cross movement	23
4) Mechanism of grinding wheel head vertical movement	23
5) Handling of the grinding wheel head	25
(1) Structure	25
(2) Grinding wheel spindle	25
(3) Change-over of the grinding wheel spindle	26
(4) Swivelling and angle setting	26
a. Horizontal swivel of the grinding wheel head (swivel of the angular base)	26
b. Swivelling of the swivel base	27
c. Tilting of the grinding wheel spindle	27
6) Tailstock and workhead	29
7) Adjustment of the swivel table	31
6. Preparations for grinding cutters	32
1) Direction of rotation of grinding wheel	32
2) Truing the wheel	33
3) Tooth rest blade and tooth rest	33
4) Grinding wheel	35
5) Center gauge	36
6) Safety precautions	38
(1) Dust insulation glasses	38

(2) Wheel guard	38
(3) Setting up of grinding wheel	38
(4) Inspection and storage of grinding wheel	39
(5) Operation rules and general precautions on works	39
7. Grinding cutters	40
1) General descriptions on grinding cutters	40
(1) Grinding peripheral teeth	40
(2) Grinding of face	44
2) Grinding a plain mill	46
(1) With a straight wheel	46
(2) With a flaring cup or straight cup	49
3) Grinding a end mill and a shell-end-mill	55
(1) Grinding end teeth	55
(2) Grinding corner	57
4) Grinding a face mill	57
5) Grinding a keyway or slotting cutter	57
6) Grinding a side milling cutter	58
7) Grinding a staggered tooth cutter	59
8) Grinding an angular cutter	61
9) Grinding a long end mill	61
10) Grinding a metal slitting saw	62
11) Grinding a large metal saw	63
12) Grinding a helical tooth cutter	64
13) Grinding a tap	66
14) Grinding a reamer	67
(1) Grinding a straight reamer	68
a. Grinding chamber portion and starting taperportion	69
b. Grinding straight portion	69
c. Grinding rake face	70
(2) Grinding a taper reamer	72
a. Grinding relief angle	72
b. Grinding rake face	72
(3) Grinding a taper reamer with helical teeth	72
8. Extra attachments	73
1) Cylindrical grinding attachment	73
2) Formed cutter grinding attachment	73

3)	Surface grinding attachment	74
4)	Internal grinding attachment	74
5)	Spring collet chuck	74
6)	No. 1 Radius grinding attachment	74
7)	No. 2 Radius grinding attachment	74
8)	Small end mill grinding attachment	74
9)	Face mill grinding attachment	74
10)	Long reamer grinding attachment	74
11)	Dust collector	74
12)	Work-head indexing attachment	74
13)	Raising block	75
14)	Mist-type coolant system	75
15)	Lathe & planer tool grinding attachment	75
16)	Drill pointing attachment	75
17)	Table reciprocating attachment	75
18)	Helical grinding attachment	75
19)	Extended grinding wheel spindle	75
20)	Optical radius grinding attachment	75
21)	Wet grinding attachment	75
22)	Hydraulic table feeds attachment	75
23)	Variable speed work-head	76
24)	Heavy duty tailstocks	76