

CNC SYSTEMS
OSP7000L Model U
OSP700L Model U

ADDITIONAL FUNCTIONS

INSTRUCTION MANUAL (2nd Edition)

Pub. No. EEL1-003-R2 Mar. 1996




TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 PROGRAM SIMULATION BY ANIMATION	1
1. ANIMATION MODE DISPLAY	2
1-1. Function Keys Used for Graphic Display Operation	2
1-2. General Precautions for Animation Mode Display	4
1-3. High Speed Drawing	5
1-4. Display Page	5
1-5. Machine Time Display	6
1-6. Additional Functions for Multi-machining Operation	6
2. TOOL FORM SELECTION	9
3. DRAWING BLANK SHAPE	11
4. HOW TO SET DRAWING POSITIONS OF CHUCK AND TAILSTOCK	24
5. SYSTEM VARIABLES FOR ANIMATION DISPLAY	26
6. CYCLE TIME CALCULATION FUNCTION	29
6-1. Cycle Time Calculation Process	29
6-2. Screen Display of Machine Time Data	30
6-3. Operation Procedure	30
SECTION 2 DNC-A	31
1. OVERVIEW	32
2. OPERATING PROCEDURES	33
2-1. Downloading an NC Program (File)	35
2-2. Uploading an NC Program (File)	36
3. SETTING UP OPTIONAL PARAMETERS	37
4. DATA FORMATS	38
5. EXAMPLE RS232C INTERFACE CONNECTIONS AND TIMING CHARTS	41