

Stray Light Measurement

Image Field Size [mm]

Steps

Apply REMA Window : Yes

Illumination Mode : Conventional

Numerical Aperture : 0.57

```
Sigma Outer      : 0.750
```

```

Illumination mode name      : conventional      Version : 1.0.0

```

Stray Light Measurement

Maximum Stray Light Number [%] : 2.46

Stray Light Variation [%] : 1.42

```
Log Files      : LI/LIUM/waf.13966, LI/LIUM/waf.13967
```