



1999 Marini MF 665 WD -010-

ENGINE	
Brand	Deutz
Type	BF6M 1012
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	4/5 good
Quality cooling liquid	3/5 good

ENGINE	
Cooling liquid level	OK
Engine oil	3/5 good
Engine leackages	no leakages
CONVEYOR CHAINS	
Condition of flight-chains in %	70%
Condition of the floor-plates in %	60%
Condition of sprockets in %	60%
SCREED	
Type of screed	HB (from 2,50m to 4,85m) gas heating
Condition of screed-plates in %	60%
Condition of tamper in %	60%
HIDRAULICS	
Speed hydraulics functions	4/5 good
Hydraulic noise	no noise
Hydraulics leackages	no leakages
CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %	
Back tyres	10%
Front tyres	60%
Remarks	front good, back to replace
BODY WORK	
Condition of the body work	80%
Condition of the paint	new yellow paint
CABIN	
Condition of the seat	10%
Condition of the dashboard	70%

- **Brand:** Marini
- **Model:** MF 665 WD
- **Year:** 1999
- **Serial number:** 0010
- **Hours:** 5.750
- **Weight:** 17 Ton
- **Screed:** HB (from 2,50m to 4,85m) gas heating
- **Leveling system/Sensors:** noting