ULTRASONIC THICKNESS INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

Technician Sign:

Technician Certification:

BRANDON FLAIG
CGSB Level II MT REG.#32777
CWB LEVEL 1 INSPECTOR
REG. #12190660

Assistant:

Date: OCT.21 2026

Client: **RARE OILFIELD**

Location: **RARE OILFIELD SHOP REDCLIFF AB.**

Client Rep Signature: KELLY HOBMAN

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #:	**BF26211**
Report #:	BF26211-U1
Page:	1 of 2
Acceptance Code:	Client Information
Specification:	Integrity Survey
Procedure:	UT-1 Rev.2
Technique:	UT - Thickness
Contractor:	RARE OILFIELD
A.F.E.#:	
Code.#:	
P.O.#:	
Project:	THICKNESS TEST
Job.#:	SERIAL #16232

100BBL TANK SERIAL #16232 THICKNESS TEST

DATA PLATE



Overview 1



OVERVIEW 2



THICKNESS TESTING PERFORMED ON VESSEL ABOVE ON RANDOM SPOTS ON SHELL/ FLOOR AND ROOF AS PER CUSTOMER. RESULTS ARE RECORDED ON THE FOLLOWING PAGE.

Equipment, Calibrations & Consumables Used

Instrument Make:	AlphaGage+, Ser: 000128	Range Of Verification: 0.1" - 0.5"	Calibrated On: OCT.21 2026	Cable Length: 3 Feet	Cable Type: Coaxial	Test Method: Thickness> ✓ Lamination>	Couplant: Sonotech Soundsafe
Transduser Settings:	Sonatest Probe	Model: DK525	Calibrated On: **OCT.21 2026**	Angle: 0°	Frequency: 5 MHz	Size: 5 / .25"	Refrence & Scan /
Calibration Block:	IIW Type 1 Refrence Block 1018 Steel Heat #C203714	Block Serial #: S/N 3142 24	Calibrated On: **OCT.21 2026**	Reference Reflector: Backwall		Refernece %FSH 100%	Range Setting 1.0 Inches

ULTRASONIC THICKNESS INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

Technician Sign:

Technician Certification:

BRANDON FLAIG
CGSB Level II MT REG.#32777
CWB LEVEL 1 INSPECTOR
REG. #12190660

Assistant:

Date: OCT.21 2026
Client: RARE OILFIELD
Location: RARE OILFIELD SHOP REDCLIFF AB.
Client Rep Signature:

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #: BF26211
Report #: BF26211-U1
Page: 2 of 2

Acceptance Code: Client Information
Specification: Integrity Survey
Procedure: UT-1 Rev.2
Technique: UT - Thickness
Contractor: RARE OILFIELD
AFE:
Code:
P.O.#:
Project: THICKNESS TEST
Job#: SERIAL #16232

Area Surface Readings: ↓		Nominal Wall Thickness:>		Average Thickness Reading:>	0.210
Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:
CML-1	0.21	0.221	CML-6	0.209	0.213
CML-2	0.206	0.213	CML-7	0.204	0.208
CML-3	0.197	0.203	CML-8	0.213	0.221
CML-4	0.201	0.211	CML-9	0.205	0.215
CML-5	0.21	0.217	CML-10	0.21	0.218



Information On Above: ↓	Material:> Carbon Steel	Surface Condition:> Painted / Coated

CML1-8 (SHELL)/ CML9-11 (ROOF)/ CML12-14 (FLOOR). RESULTS ARE RECORDED IN INCHES.

Area Surface Readings: ↓		Nominal Wall Thickness:>		Average Thickness Reading:>	0.250
Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:
CML-11	0.212	0.222	CML-6		
CML-12	0.257	0.262	CML-7		
CML-13	0.261	0.266	CML-8		
CML-14	0.257	0.263	CML-9		
CML-5			CML-10		



Information On Above: ↓	Material:> Carbon Steel	Surface Condition:> Painted / Coated

CML1-8 (SHELL)/ CML9-11 (ROOF)/ CML12-14 (FLOOR). RESULTS ARE RECORDED IN INCHES.