



MT / PT INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
office@slickinspection.com

Technician Sign:

Technician Certification:

JOHN MARTIN
CGSB Level II RT MT PT
SNT-TC-1A Level II RT MT PT
REG. #27301

Assistant:

Date:
Client:

MAR. 27, 2025

RARE OILFIELD

Location:

**RARE OILFIELD, REDCLIFF
AB**

Client Rep Signature:

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #:

JM25094

Report #:

JM25094-M2

Page:

1 of 3

Acceptance Code:

ASME Sec.VIII, Div. 1 2023

Specification:

MT-Rev.8

Procedure:

MT 2 - Wet Visible, Black On White

Technique:

Contractor:

RARE OILFIELD

A.F.E.#:

Code.#:

P.O.#:

Project:

Job.#:

FIRE TUBES 'A' AND 'B'

VESSEL NAME PLATE:



FIRE TUBES:



PREFORMED MAG PARTICAL INSPECTION ON ALL PROCESS WELDS AND AREAS OF INTEREST OF FIRE TUBES 'A' AND 'B'.

Equipment & Consumables Used	Flourescent>	Black/White>	✓	Aerosol>	✓	Visible>	✓	Dry>	Puffer>
MT 2: Magnavis White Contrast Paint: WCP-2 / Magnavis Black Partical Suspension: 7HF		Calibration Block: West. Instruments S/N:6429 Cal Verified to 10lb Daily		Continues AC Current Mag Lead Time: 10 Seconds LED Flasfh light>		Sentenial Yoke: MP-A-2L S/N: MP4083		Light Meter:XR-1000 Spectronics S/N:1752289 Cal Date: May 31,2024 Min Light Intensity: ≥ 100 FC Visible	



SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
office@slickinspection.com

MT / PT INSPECTION REPORT

Technician Sign: 

Technician Certification:

JOHN MARTIN
CGSB Level II RT MT PT
SNT-TC-1A Level II RT MT PT
REG. #27301

Assistant:

Date:
Client:

MAR. 27, 2025

RARE OILFIELD

Location:

**RARE OILFIELD, REDCLIFF
AB**

Client Rep Signature:

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #:

JM25094

Report #:

JM25094-M2

Page:

2 of 3

Acceptance Code:

ASME Sec.VIII, Div. 1 2023

Specification:

MT-Rev.8

Procedure:

MT 2 - Wet Visible, Black On White

Technique:

Contractor:

RARE OILFIELD

A.F.E.#:

Code.#:

P.O.#:

Project:

Job.#:

FIRE TUBE 'A'



Information On Above: ↓ Material:> Carbon Steel Surface Condition:> Base Metal

LINEAR INDICATIONS FOUND ON AREAS INDICATED IN ABOVE PHOTOS

FIRE TUBE 'A' INDICATION



Information On Above: ↓ Material:> Carbon Steel Surface Condition:> Base Metal

LINEAR INDICATIONS FOUND ON AREAS INDICATED IN ABOVE PHOTOS



MT / PT INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
office@slickinspection.com

Technician Sign: 

Technician Certification:

JOHN MARTIN
CGSB Level II RT MT PT
SNT-TC-1A Level II RT MT PT
REG. #27301

Assistant:

Date: MAR. 27, 2025
Client:

RARE OILFIELD

Location: **RARE OILFIELD, REDCLIFF**
AB

Client Rep Signature:

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #:

JM25094

Report #:

JM25094-M2

Page:

3 of 3

Acceptance Code:

ASME Sec.VIII, Div. 1 2023

Specification:

MT-Rev.8

Procedure:

MT 2 - Wet Visible, Black On White

Technique:

Contractor:

RARE OILFIELD

A.F.E.#:

Code.#:

P.O.#:

Project:

Job.#:

FIRE TUBE 'B'



Information On Above: ↓ Material:> Carbon Steel Surface Condition:> Base Metal

NO RELEVANT INDICATIONS FOUND AT TIME OF INSPECTION

FIRE TUBE 'B'



Information On Above: ↓ Material:> Carbon Steel Surface Condition:> Base Metal

NO RELEVANT INDICATIONS FOUND AT TIME OF INSPECTION