ULTRASONIC THICKNESS INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

Technician Sign:

Technician Certification:

BRANDON FLAIG
CGSB Level II MT REG.#32777
CWB LEVEL 1 INSPECTOR
REG. #12190660

Assistant:

Date: OCT.21 2026

Client: **RARE OILFIELD**

Location: **RARE OILFIELD SHOP REDCLIFF AB.**

Client Rep Signature: KELLY HOBMAN

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #:	**BF26213**
Report #:	BF26213-U1
Page:	1 of 2
Acceptance Code:	Client Information
Specification:	Integrity Survey
Procedure:	UT-1 Rev.2
Technique:	UT - Thickness
Contractor:	RARE OILFIELD
A.F.E.#:	
Code.#:	
P.O.#:	
Project:	400BBL TANK
Job.#:	TANK SERIAL #16243

400BBL TANK SERIAL #16243 THICKNESS TEST

DATA PLATE



Overview 1



OVERVIEW 2



THICKNESS TESTING PERFORMED ON VESSEL ABOVE ON RANDOM SPOTS ON SHELL/ FLOOR AND ROOF AS PER CUSTOMER.RESULTS ARE RECORDED ON THE FOLLOWING PAGE.

Equipment, Calibrations & Consumables Used

Instrument Make:	AlphaGage+, Ser: 000128	Range Of Verification: 0.1" - 0.5"	Calibrated On: OCT.21 2026	Cable Length: 3 Feet	Cable Type: Coaxial	Test Method: Thickness> ✓ Lamination>	Couplant: Sonotech Soundsafe
Transduser Settings:	Sonatest Probe	Model: DK525	Calibrated On: **OCT.21 2026**	Angle: 0°	Frequency: 5 MHz	Size: 5 / .25"	Refrence & Scan /
Calibration Block:	IIW Type 1 Refrence Block 1018 Steel Heat #C203714	Block Serial #: S/N 3142 24	Calibrated On: **OCT.21 2026**	Reference Reflector: Backwall		Refernece %FSH 100%	Range Setting 1.0 Inches

ULTRASONIC THICKNESS INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

Technician Sign:

Technician Certification:

BRANDON FLAIG
CGSB Level II MT REG.#32777
CWB LEVEL 1 INSPECTOR
REG. #12190660

Assistant:

Date: OCT.21 2026
Client: RARE OILFIELD
Location: RARE OILFIELD SHOP REDCLIFF AB.
Client Rep Signature:

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #: BF26213
Report #: BF26213-U1
Page: 2 of 2

Acceptance Code: Client Information
Specification: Integrity Survey
Procedure: UT-1 Rev.2
Technique: UT - Thickness
Contractor: RARE OILFIELD
AFE:
Code:
P.O.#:
Project: 400BBL TANK
Job#: TANK SERIAL #16243

Area Surface Readings: ↓		Nominal Wall Thickness:>		Average Thickness Reading:>	0.191
Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:
CML-1	0.188	0.194	CML-6	0.187	0.195
CML-2	0.191	0.196	CML-7	0.187	0.191
CML-3	0.183	0.188	CML-8	0.187	0.193
CML-4	0.187	0.193	CML-9	0.191	0.197
CML-5	0.19	0.195	CML-10	0.194	0.199



Information On Above: ↓	Material:>	Carbon Steel	Surface Condition:>	Sandblasted

CML1-12 (SHELL)/ CML13-16 (FLOOR/ CML17-20 (ROOF). RESULTS ARE RECORDED IN INCHES.

Area Surface Readings: ↓		Nominal Wall Thickness:>		Average Thickness Reading:>	0.213
Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:
CML-11	0.189	0.198	CML-16	0.242	0.26
CML-12	0.199	0.205	CML-17	0.172	0.18
CML-13	0.259	0.264	CML-18	0.177	0.181
CML-14	0.248	0.254	CML-19	0.176	0.182
CML-15	0.256	0.261	CML-20	0.177	0.186



Information On Above: ↓	Material:>	Carbon Steel	Surface Condition:>	Sandblasted

CML1-12 (SHELL)/ CML13-16 (FLOOR/ CML17-20 (ROOF). RESULTS ARE RECORDED IN INCHES.