

Integration Report

Machine Serial Number	VN113002	12.07.2011 10:51:23 SERGY
Camerahead Serial Number	FLX111028	12.07.2011 10:54:08 SERGY
Tester Type	4-25	12.07.2011 10:54:12 SERGY
Top Camera Type	DALSA PT-41 04M60	12.07.2011 10:54:14 SERGY
Angled Camera Type	SONY XC-HR70	12.07.2011 10:54:16 SERGY
Angled Repair Camera Type	None	12.07.2011 10:54:19 SERGY
Color Option	Enabled	12.07.2011 10:54:20 SERGY
Enable 60Hz Mode	Disabled	12.07.2011 10:54:21 SERGY
Machine Type	Vantage	12.07.2011 10:54:23 SERGY
Fast Exchange Unit	Disabled	12.07.2011 10:54:24 SERGY
Dual Lane	Disabled	12.07.2011 10:54:25 SERGY
Left Conveyor	Disabled	12.07.2011 10:54:25 SERGY
Right Conveyor	Disabled	12.07.2011 10:54:26 SERGY
Motor X	OK	12.07.2011 10:57:58 SERGY
Motor Y	OK	12.07.2011 10:58:15 SERGY
Motor Z	OK	12.07.2011 10:58:31 SERGY
Stage Conveyor Width	OK	12.07.2011 10:59:10 SERGY
Measure Traverse Path	OK	13.07.2011 09:46:46 SERGY
Measure Smooth Running	OK	13.07.2011 09:58:43 SERGY
Setup Reference Width	OK	12.07.2011 11:00:04 SERGY
Setup Calibration Height	3.29 mm	12.07.2011 13:34:13 SERGY
Camera Alignment	OK	13.07.2011 09:25:22 SERGY
Sharpness Adjustment	OK	12.07.2011 15:54:52 SERGY
Top Camera Calibration	Not done	
Brightness Adjustment	OK	12.07.2011 15:54:52 SERGY
Flash Alignment	OK	13.07.2011 09:40:28 SERGY
Line Projector Alignment	OK	13.07.2011 09:25:22 SERGY
Flash Level Adjustment	OK	13.07.2011 09:42:11 SERGY
Grid Adjustment	OK	13.07.2011 10:15:04 SERGY
Adapter Calibration	OK	13.07.2011 10:34:17 SERGY
Angle Distortion Calibration	-0.20 mm/m	13.07.2011 10:34:17 SERGY
Finish Integration	OK	13.07.2011 11:27:01 SERGY