



1992 Massenza B7

ENGINE	
Brand	Hatz
Type	
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK

ENGINE	
Blow by	3/5 good
Quality cooling liquid	3/5 good
Cooling liquid level	OK
Engine oil	3/5 good
Engine leackages	no leakages
CONVEYOR CHAINS	
Condition of flight-chains in %	
Condition of the floor-plates in %	
Condition of sprockets in %	
SPRAY BAR	
Type of bar	Fix bar 2.5m
UP / DOWN	Manual
Nozzles	Air
HIDRAULICS	
Speed hydraulics functions	3/5 good
Hydraulic noise	no noise
Hydraulics leackages	no leakages
CONDITION OF THE TANK	
Overall conditions	good
Capacity	7.000 liters
Remarks	5.000L emulsion + 2.000L water
BODY WORK	
Condition of the body work	60%
Condition of the paint	new paint
CABIN	
Condition of the seat	
Condition of the dashboard	

- **Brand:** Massenza
- **Model:** B7
- **Year:** 1992
- **Serial number:** 0112
- **Hours:**
- **Weight:** 0,7 ton
- **Spray bar:** Fix bar 2,5m / air open