

## 2011 Vogele Super 800 -288-

ENGINE	
Brand	Deutz
Туре	TCD 2011 L03 (45Kw)
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	4/5 good
Quality cooling liquid	4/5 good

ENGINE		
Cooling liquid level	OK	
Engine oil	4/5 good	
Engine leackages	no leakages	
CONVEYOR CHAINS		
Condition of flight-chains in %	80%	
Condition of the floor-plates in %	60%	
Condition of sprockets in %	80%	
SCREED		
Type of screed	AB 200 TV 1,10/2,00 + n.2 extentions 0,60m each	
Condition of screed-plates in %	70%	
Condition of tamper in %	70%	
HIDRAULICS		
Speed hydraulics functions	4/5 good	
Hydraulic noise	no	
Hydraulics leackages	no leakages	
CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %		
Overall conditions	60%	
Pads	60%	
Remarks	good conditions	
BODY WORK		
Condition of the body work	70%	
Condition of the paint	new paint	
CABIN		
Condition of the seat		
Condition of the dashboard	60%	

• Brand: Vogele

■ Model: Super 800

• **Year**: 2011

• **Serial number:** 07901288

Hours: 5.836Weight: 6,3 Ton

**Screed:** 1,10/2,00 + n.2 extentions 0,60m each