



## 1992 Bitelli SF 100 -159-

ENGINE	
Brand	Deutz
Type	BF6L 913
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK
ENGINE	
Blow by	3/5 good
Quality cooling liquid	3/5 good

<b>ENGINE</b>	
Cooling liquid level	OK
Engine oil	3/5 good
Engine leackages	no leackages
<b>CONVEYORS</b>	
Conditions of small conveyor in %	No
Conditions of big conveyor in %	70%
Leveling System	original leveling system
<b>DRUM</b>	
Width of drum	1000 mm width / 240 mm depth
Condition of tool-holder in %	60%
Condition of teeth %	40%
<b>HIDRAULICS</b>	
Speed hydraulics functions	3/5 good
Hydraulic noise	no noise
Hydraulics leackages	not important leakages
<b>CONDITION OF THE UNDERCARRIAGE REMAINING FROM NEW IN %</b>	
Back tyres	50%
Front tyres	50%
Remarks	nothing
<b>BODY WORK</b>	
Condition of the body work	70%
Condition of the paint	
<b>CABIN</b>	
Condition of the seat	no seats
Condition of the dashboard	70%

- **Brand:** Bitelli
- **Model:** SF 100
- **Year:** 1992
- **Serial number:** 388920159
- **Hours:** 4.443
- **Weight:** 13 Ton
- **Drum:** 1000 mm width / 240mm depth
- **Leveling system:** nothing