



2000 Corinsa CCR 1421

ENGINE	
Brand	Deutz
Type	912 F6L
GENERAL	
Hydraulic oil checked	YES OK
Engine oil checked	YES OK
Diesel checked	YES OK

ENGINE	
Blow by	3/5 good
Quality cooling liquid	3/5 good
Cooling liquid level	OK
Engine oil	3/5 good
Engine leakages	no leakages
TYRES / BRAKES	
Condition of tyres in %	80%
Brakes in %	OK
Tyres/drums	n.7 tyres
HIDRAULICS / TRANSMISSION	
Speed hydraulics functions	3/5 good
Hydraulic noise	no noise
Hydraulics leakages	no leakages
CE certificate	Yes
A/C clima	No
BODY WORK	
Condition of the body work	80%
Condition of the paint	new paint
CABIN	
Condition of the seat	70%
Condition of the dashboard	50%

- **Brand:** Corinsa
- **Model:** CR 1421
- **Year:** 2000
- **Serial number:** 1421/112
- **Hours:** 3.740
- **Weight:** 21 Ton
- **Optionals:** Closed cabin